

PatternSmith Shortcut Keys

Project Window

Menu	Command	Key Combo	alt codes		
Quick Access			alt- #		
File	New	ctrl+n	alt- f- n		
	Open	ctrl+o	alt- f- o		
	Recent		alt- f- r		
	Save	ctrl+s	alt- f- s		
	Save As	ctrl+shift+s	alt- f- a		
	Import	F9, ctrl+shift+i	alt- f- i		
	Export	F8, ctrl+shift+e	alt- f- x		
	Export Nest	F7	alt- f- t		
	Print	ctrl+p	alt- f- p		
	Preferences	ctrl+shift+p	alt- f- e		
	Help	F1	alt- f- h		
	Close All	ctrl+shift+w	alt- f- c		
	Exit	alt+F4	alt- f- q		
Nest	Nestle	space	alt- n- n		
	Move Freely	space	alt- n- m		
	Auto Fit	ctrl+shift+f	alt- n- u		
	Free Zoom	ctrl+shift+f	alt- n- z		
	Snap Horizontal	ctrl+shift+h	alt- n- h		
	Snap Vertical	ctrl+shift+v	alt- n- v		
	Copy	ctrl+shift+c	alt- n- c		
	Array	ctrl+d	alt- n- a		
	Material Library	ctrl+m	alt- n- l		
	Next Table	ctrl+right	alt- n- t		
	Previous Table	ctrl+left	alt- n- p		
	Show Overlaps	ctrl+shift+o	alt- n- o		
	Show Out of Bounds	ctrl+shift+b	alt- n- b		
	Stop Checking Bounds	ctrl+alt+b	alt- n- x		
	NestFab	F11	alt- n- f		
NestFab	shift+F11				

	Scapos	F11	alt- n- s	
Patterns	Editor	F5, ctrl+e	alt- p- e	
	Copy	ctrl+shift+c	alt- p- c	
	Array	ctrl+d	alt- p- a	
	Create Box Pattern	alt+b	alt- p- b	
	Scale Selected	ctrl+alt+s	alt- p- gs	
	Combine Selected	ctrl+j	alt- p- gc	
	Extract Patterns	ctrl+alt+e	alt- p- p	
	Modify Notches	ctrl+shift+n	alt- p- n	
	Modify Text Elements	ctrl+shift+t	alt- p- t	
	Optimize	ctrl+r	alt- p- o	
	NestFab	F11	alt- p- f	
	Scapos	F11	alt- p- s	
Tools	CadShot Properties	ctrl+alt+y	alt- t- c	
	Load Cadshot File	ctrl+alt+p	alt- t- l	
	CadShot Vision	ctrl+alt+v	alt- t- v	
	Slicer	ctrl+l	alt- t- s	
	Templates	ctrl+t	alt- t- t	
	Generate Patterns	ctrl+g	alt- t- g	
Plot/Cut	Properties		alt- c- cp	
	Shutdown	shift+F4	alt- c- s	
	Import		alt- c- i	
	Export		alt- c- e	
	Add		alt- c- a	
	Remove		alt- c- r	
	Plot Options	ctrl+alt+o	alt- c- o	
	Plot to File		alt- c- f	
	Current Table	F10	alt- c- ct	
	Current Selection	shift+F10	alt- c- cs	
	Previous Table	ctrl+left	alt- c- p	
Next Table	ctrl+right	alt- c- t		
View	Cascade		alt- v- c	
	Tile Horizontally		alt- v- h	
	Tile Vertically		alt- v- v	

	Zoom All	ctrl+space	alt- v- a		
	Zoom Selection	F12	alt- v- s		
	Zoom to Pattern	shift+F12	alt- v- p		
	Show Pattern Names	F3	alt- v- n		
	Show Pattern Labels	F4	alt- v- l		
	Show Placement Groups	F6	alt- v- g		
	Show Table Rulers		alt- v- r		
	Reset Layout		alt- v- t		
No Button	Close Active Document	ctrl+w			
	Move Patterns	left			
		right			
		up			
		down			
	Move Patterns - Tighten Spacing	shift+left			
		shift+right			
		shift+up			
shift+down					
Windows Default	Copy	ctrl+c			
	Cut	ctrl+x			
	Paste	ctrl+v			
	Select All	ctrl+a			
	Undo	ctrl+z			
	Redo	ctrl+y, ctrl+shift+z			

Editor Window

Menu	Command	Key Combo	alt codes
File	New	ctrl+p	alt- f- n
	Open	ctrl+o	alt- f- o
	Save All	ctrl+s	alt- f- a
	Save Selected		alt- f- s
	Preferences	ctrl+shift+p	alt- f- p
	Help	F1	alt- f- h
	Done	ctrl+d	alt- f- d

	Cancel	ctrl+alt+d	alt-	f-	c			
Toolbar	Selector	s						
	Alternate Selector	t						
	Measure	m						
	Mark	shift+m						
	Print	shift+b						
	Cut	shift+c						
	Cut 2	shift+a						
	Drill	shift+d						
	Crease	shift+v						
	Reference	shift+r						
	Open Entity	ctrl+shift+o						
	Close Entity	ctrl+shift+x						
	Spline	ctrl+alt+s						
	Polyline	ctrl+alt+l						
	Group	ctrl+g						
	Ungroup	ctrl+alt+g						
	Alignment - Primary	ctrl+alt+1						
	Alignment - Secondary	ctrl+alt+2						
	Alignment - Clear	ctrl+alt+0						
	Seam Ends	ctrl+alt+e						
	Seams		ctrl+1					
			ctrl+2					
			ctrl+3					
		ctrl+4						
		ctrl+5						
Convert Seams to Elements	ctrl+e							
Remove Seams	ctrl+0							
Design	Done	ctrl+d	alt-	d-	p	d		
	Cancel	ctrl+alt+d	alt-	d-	p	c		
	Make new Pattern	ctrl+p	alt-	d-	p	d	n	
	Point	p	alt-	d-	c	p		
	Lines - Line	l	alt-	d-	c	l	l	
	Lines - Polyline	y	alt-	d-	c	l	p	

Curves - Bezier	b	alt-d-c-c-b
Curves - Spline	e	alt-d-c-c-s
Conics - Arc	a	alt-d-c-o-a
Conics - Circle	c	alt-d-c-o-c
Conics - Ellipse	i	alt-d-c-o-e
Polygons - Rectangle	r	alt-d-c-r-r
Polygons - Polygon	g	alt-d-c-r-p
Texts - Text	w	alt-d-c-t-t
Texts - Barcode	ctrl+w	alt-d-c-t-b
Notches - Single	ctrl+shift+n	alt-d-c-n-s
Notches - Midpoint	ctrl+shift+m	alt-d-c-n-m
Notches - Evenly Spaced	ctrl+shift+e	alt-d-c-n-e
Anchor	ctrl+alt+p	alt-d-c-a
Origin	ctrl+alt+o	alt-d-e-o
Break	ctrl+alt+b	alt-d-e-b
Points - Add / Remove	ctrl+=	alt-d-e-p-a
Points - Point at Distance	ctrl+shift+=	alt-d-e-p-d
Align - Horizontal	ctrl+[alt-d-e-a-h
Align - Parallel	ctrl+]	alt-d-e-a-p
Length	ctrl+l	alt-d-e-l
Extend/Trim	x	alt-d-e-x
Mirror	ctrl+m	alt-d-e-m
Join	ctrl+j	alt-d-a-j
Reverse	ctrl+r	alt-d-a-v
Flip - Horizontal	ctrl+alt+h	alt-d-a-f-h
Flip - Vertical	ctrl+alt+v	alt-d-a-f-v
Merge		alt-d-a-m
Move	ctrl+alt+m	alt-d-a-i
Rotate	ctrl+alt+r	alt-d-a-r
Scale	ctr+shift+s	alt-d-a-s
Thin	ctrl+t	alt-d-a-t
Circles to Points	ctrl+shift+c	alt-d-a-p
Duplicate - Delta	shift+k	alt-d-a-d-d
Duplicate - Array	shift+l	alt-d-a-d-a

	Duplicate - Polar Array	shift+p	alt- d- a d p
	Duplicate - Offset		alt- d- a d o
	Duplicate - Place		alt- d- a d c
	Duplicate - Offset/Trim	shift+o	alt- d- a d t
	Spline	shift+s	alt- d- r s
	Arc Fit	shift+f	alt- d- r a
	Arc Offset	shift+u	alt- d- r o
	Bezier	shift+j	alt- d- r b
	Bezier Fit	shift+i	alt- d- r z
	Fillet - Arc	f	alt- d- r f a
	Fillet - Bezier	j	alt- d- r f b
	Guides - Normal	shift+h	alt- d- g g n
	Guides - Angle	shift+y	alt- d- g g a
	Guides - Tangent	shift+t	alt- d- g g t
	Guides - Distance	shift+g	alt- d- g g d
	Erase	shift+x	alt- d- g e
Perimeter	Done	ctrl+d	alt- p- p d
	Cancel	ctrl+alt+d	alt- p- p c
	Box	ctrl+shift+u	alt- p- b
	Elements	ctrl+u	alt- p- e
	No Mark		alt- p- m
	No Reference		alt- p- r
Cut Ready	Done	ctrl+d	alt- c- p d
	Cancel	ctrl+alt+d	alt- c- p c
	Setup		alt- c- s
	Optimize	o	alt- c- o
	Perimeter Start		alt- c- t
	Internal Order		alt- c- i
View	Done	ctrl+d	alt- v- p d
	Cancel	ctrl+alt+d	alt- v- p c
	Zoom All	ctrl+space	alt- v- a
	Zoom Selection	F12	alt- v- s
	Zoom Background Image	shift+F12	alt- v- b
	Clear All Originals	ctrl+q	alt- v- c

	Reset Layout		alt-	v-	t				
No Button	Invert Selection	ctrl+shift+a							
	Select notch close to point	n							
	Selection Filter	ctrl+f							
	Repeat last tool	enter							
		F4							
Break geometry at corners	ctrl+b								
Windows Default	Copy	ctrl+c							
	Cut	ctrl+x							
	Paste	ctrl+v							
	Select All	ctrl+a							
	Undo	ctrl+z							
	Redo	ctrl+y, ctrl+shift+z							